

1813-1817 S Viewcrest Lane Septic Tank Location



The septic tank openings for 1813-1817 S Viewcrest Ln are located directly east and just outside the fence of 1817 S Viewcrest Ln. (Note the blue dot.) There is one opening that is within a rectangular concrete pad with a 24” circular lid. It is immediately accessible when the concrete lid is lifted. The actual location of the second opening is not shown here, but the CS Inspection report below gives some indication of its location.



PO Box 19066
Spokane, WA 99219
(509) 926-9361

SEPTIC SYSTEM INSPECTION REPORT

Inspection Date: 12-17-19 Service Order Number: 2019 Technician Name: *Shelley Leibel*
Service Address: 1817 S Viewcrest Ln City: *Spokane* State: *WA*
Property Appears Occupied: ☒ Septic System in Use ☐ No ☐ No ☐ No

System Type: ☒ Gravity Flow ☐ Pressurized with Pump ☐ Sand Mound ☐ Sand Filter ☐ Compost Toilet ☐ Single ☒ Double

Septic Tank	Sand Filter	Pump Tank
Tank Size: 1750 (Gallons)	Downflow: (Inches/Minute)	Downflow: (Inches/Minute)
Inlet Comp: 2 (Inches)	Liquid Level Normal: Yes No	Tank Size: (Gallons)
Storage: 8 (Inches)		
Scum: 35 (Inches)		
Sludge: 2 (Inches)		
Liquid Level Normal: Yes No	Disposal Area (Downflow):	Liquid Level Normal: Yes No
Sanitary Bathing: ☒ Not OK	Effluent Function? Yes ☒ No ☐	Pumping Done: Yes No
Sanitary Bathing: ☒ Not OK	Water Test Performed? Yes ☒ No ☐	Pump Pump: OK Not OK
Sanitary Bathing: ☒ Not OK	If Yes, Minutes Closed: 15-20	

System & Components Appear to be Functioning Properly at Time of Service? ☒ YES ☐ NO

Comments/Maintenance Items Needed:
Septic system was inspected and found to be in good working condition. Thanks!

Sketch of Septic System:
Sketch showing a rectangular tank with a circular lid, labeled 'Pump' and 'Depth: 50" (40" max)'.